



Hubshell

100

110

A NDS Flange \varnothing

47mm

47mm

B NDS Center to Flange

23mm

28mm

C DS Center to Flange

37mm

42mm

D DS Flange \varnothing

44mm

44mm

Positive 1.5mm offset

For Flange to Dropout Value Subtract Center to Flange Value from 1/2 of Dropout Spacing